

Material Safety Data Sheet [OSHA 29 CFR 1910.1200]

The QUIKRETE® Companies One Securities Centre 3490 Piedmont Road, Suite 1300 Atlanta, GA 30329 Emergency Telephone Number (770) 216-9580

Information Telephone Number

(770) 216-9580

Revision: July 2003 MSDS N

SECTION I: PRODUCT IDENTIFICATION

QUIKRETE® Product Name
THERMO-LUBE Code #
1905

SECTION II - HAZARDOUS INGREDIENTS/IDENTITY INFORMATION

Hazardous Components CAS No. PEL (OSHA) TLV (ACGIH)

 mg/M^3 mg/M^3

Calcium Chloride 10043-52-4 ---

SECTION III - PHYSICAL/CHEMICAL CHARACTERISTICS

Solubility in Water: Dilutable

Physical appearance and odor:

Blue liquid, odorless

Melting or freezing point: 0°C/32°F water; Boiling Point: 100°C/212°F

SECTION IV - FIRE AND EXPLOSION HAZARD DATA

Flammability: Noncombustible and not explosive.

SECTION V - REACTIVITY DATA

Stability: Stable. Is not incompatible with other minerals, will not decompose into hazardous by-products and will not polymerize.

SECTION VI - HEALTH HAZARD DATA

May irritate or burn eyes. May cause skin irritation.

Emergency First Aid Procedures: Irrigate (flood) eyes immediately for 15 minutes. Wash exposed skin areas with soap and water. If swallowed, induce vomiting immediately by giving two glasses of water and sticking finger down throat. Call physician.

SECTION VII - PRECAUTIONS FOR SAFE HANDLING AND USE

Use waterproof gloves, and wear safety glasses wish side shields.



MSDS N

Product: THERMO LUBE

SECTION VIII - CONTROL MEASURES

If spilled soak up with absorbent material, flush remainder with water. Flush to sewer if permitted by applicable local, state and federal regulations. Store in a cool place, avoid freezing.

NOTE: The information and recommendations contained herein are based upon data believed to be correct. However, no guarantee or warranty of any kind, express or implied, is made with respect to the information contained here in.